

Roland SERVICE INFORMATION
SERVICE DEPARTMENT

NO. 100215-(2)
DATE Oct. 13, 1984

PRODUCT AFFECTED: _____

TO SERVICE ENGINEERS: SUBJECT

Supplemental Information related with
Service Information No.100215

The current OC-8 includes DCB Cable H146(Flat-Flat type) for OP-8. However, this cable cannot use for "OP-8M" (CV-DCB/MIDI Interface). Because OP-8M has only DCB and MIDI Connectors, not Flat Connector. So this time, we changed the accessory DCB Cable of OC-8 form DCB Cable H146 to DCB Cable H231 (Flat-Amphenol type) for connecton with OP-8M.

H146(Flat-Flat)
OP-8 -----> JP-8(w/OC-8)

H231(Flat-Amphenol)
OP-8M -----> JP-8(w/OC-8)

^{10/13} RUS. US (Tsuruta), RCA, DK(10), Sweden, Norway
RUK. RWG. RCM. Swiss, France, Spain,
Italy, Austria, BNLX. Mexico, New Zealand,
Zmland, Greece. Swee Lee, Tom Lee.